

	GROUP Transmission	MODEL 2020MY~ Soul (SK3)
	NUMBER PS605	DATE April 2019
 		
DIFFICULT TO SHIFT INTO 1 ST GEAR		

This Pitstop provides information regarding a possible difficult to shift into 1st gear concern on 2020MY Soul (SK3) vehicles equipped with manual transmissions. The possible root cause could be that the shift/control cable is out of adjustment. To correct the concern, refer to KGIS service manual, **Manual Transaxle System → Manual Transaxle Control System → Control Cable → Repair Procedures.**

